

FOR ALL VENUE RISK ASSESSMENTS PLEASE GO TO

<https://www.dclt.co.uk/hatfield-outdoor-activity-centre-campsite/centre-info/group-resources/>

INDIVIDUAL GAME RISK ASSESSMENTS BELOW

RISK ASSESSMENT – Catch It

HAZARD	EXISTING CONTROL MEASURES	HARM (1-5)	LIKELY HOOD (1-5)	RISK (1-5)	FURTHER CONTROLS TO REDUCE RISK	RISK ACCEPTABLE Y/N
Over enthusiastic participants	Supervision at all times	1	1	1	Fencing off the area if required	Yes
Objects falling	Start button to be pressed when game play commences and children are away from the play zone.	1	1	1	No sharp objects to be used	Yes
Unit Tipping over	Ensure legs are fully locked into place.	1	1	1	Set up on flat level surface	Yes
RISK ASSESSMENT CARRIED OUT BY:	B AUTY	DATE: 09/03/23		ANY OTHER ACTION REQUIRED:	Ensure that operators follow all 'Operating Instructions' as supplied	

THE ABOVE INFORMATION IS BASED ON MAUFACTURERS
CRITERIA AND EXPERIENCE FROM EXTENSIVE USE OF EQUIPMENT.

SIGNATURE: *B.AUTY*

RISK ASSESSMENT – CHELTENHAM PONY CHASE

HAZARD	EXISTING CONTROL MEASURES	HARM (1-5)	LIKELY HOOD (1-5)	RISK (1-5)	FURTHER CONTROLS TO REDUCE RISK	RISK ACCEPTABLE Y/N
Over enthusiastic participants	Adult supervision at all times	1	1	1		
Slipping on the equipment	Adult supervision at all times	1	1	1	Do not use when raining or wet.	
Larger participants colliding with smaller participants	Adult supervision at all times.	1	1	1	Participants put into groups of similar size.	
Tripping over anchorage points/spare equipment/electrical cable	All anchor points used as per manufacturers instructions and spare equipment leads etc either stowed / erected safely	1	1	1	In event of large numbers of participants attending, additional safety fencing erected. Where possible electrical cable does not cross any public pathway. If unavoidable cable erected overhead or covered.	
Petrol Blower/Generator Risk of fire or burning	Safety fencing erected around the items. Suitable fire extinguisher supplied.	3	1	1	All spare fuel stored in suitable container and in a safe location. Units switched off during refuelling.	
RISK ASSESSMENT CARRIED OUT BY:	Brian Auty		DATE: 22/03/23	ANY OTHER ACTION REQUIRED:	Ensure that operators follow all 'Operating Instructions' as supplied	

THE ABOVE INFORMATION IS BASED ON MAUFACTURERS CRITERIA AND EXPERIENCE FROM EXTENSIVE USE OF EQUIPMENT.

RISK ASSESSMENT – Equaliser

HAZARD	EXISTING CONTROL MEASURES	HARM (1-5)	LIKELY HOOD (1-5)	RISK (1-5)	FURTHER CONTROLS TO REDUCE RISK	RISK ACCEPTABLE Y/N
Over enthusiastic participants	Adult supervision at all times	1	1	1		YES
Jumping off unit	Adult supervision at all times	1	1	1	Additional safety mats in front of unit exit.	YES
Injury to participants	Adult supervision at all times.	1	1	1	When the participant is about to be pulled back by the bungee cord make sure they fall naturally and not to jump in the air.	YES
Tripping over anchorage points/spare equipment/electrical cable	All anchor points used as per manufacturers instructions and spare equipment leads etc either stowed / erected safely	1	1	1	In event of large numbers of participants attending, additional safety fencing erected. Where possible electrical cable does not cross any public pathway. If unavoidable cable erected overhead or covered.	YES
Petrol Blower/Generator Risk of fire or burning	Safety fencing erected around blower/generator. Suitable fire extinguisher supplied.	3	1	1	All spare fuel stored in suitable container and in a safe location. Units switched off during refuelling.	YES
RISK ASSESSMENT CARRIED OUT BY:	Brian David Auty		DATE: 16/3/23	ANY OTHER ACTION REQUIRED	Ensure that operators follow all 'Operating Instructions' as supplied or Active Hire to provide experienced staff for safe equipment supervision	

RISK ASSESSMENT – Pedal Karts

HAZARD	EXISTING CONTROL MEASURES	HARM (1-5)	LIKELY HOOD (1-5)	RISK (1-5)	FURTHER CONTROLS TO REDUCE RISK	RISK ACCEPTABLE Y/N
Over enthusiastic participants	Adult supervision at all times	1	1	1		Yes
Participants falling from the Kart – Body Injuries	Full Instructions on how to adjust seat to correct position given	2	1	2		Yes
Weather – high wind and rain	Supervised at all times	1	1	1	In the event of high winds or rain suitable footwear must be worn when riding the karts. Karts may be stopped at the operator's discretion.	Yes
Karts colliding with others or static objects	Adult supervision at all times. Only 4 Karts on the track	1	2	3	Only competent persons to use karts, arena to be set up at the operators discretion if risks are too high and used by children under 16.	Yes
RISK ASSESSMENT CARRIED OUT BY:	Brian Auty	DATE: 22/04/2024		ANY OTHER ACTION:		Ensure that operators follow all 'Operating Instructions' verbally supplied

THE ABOVE INFORMATION IS BASED ON MANUFACTURERS CRITERIA AND EXPERIENCE FROM EXTENSIVE USE OF EQUIPMENT.

B D AUTY

Signature _____

RISK ASSESSMENT – POLE JOUST

HAZARD	EXISTING CONTROL MEASURES	HARM (1-5)	LIKELY HOOD (1-5)	RISK (1-5)	FURTHER CONTROLS TO REDUCE RISK	RISK ACCEPTABLE Y/N
Over enthusiastic participants	Adult supervision at all times	1	1	1		Yes
Participants being fallen on	Adult supervision at all times	1	1	1	No more than two on the inflatable at the same time. No sitting around the edges.	Yes
Larger participants colliding with smaller participants	Adult supervision at all times.	1	1	1	Participants put into groups of similar size.	Yes
Tripping over anchorage points/spare equipment/electrical cable	All anchor points used as per manufacturers instructions and spare equipment leads etc either stowed / erected safely	1	1	1	In event of large numbers of participants attending, additional safety fencing erected. Where possible electrical cable does not cross any public pathway. If unavoidable cable erected overhead or covered.	Yes
Impact injuries	Head guards supplied for use with the equipment and padded platform rims	2	2	1	Light weight padded bags	Yes
In climate Weather	The unit will not be operated in wet weather and if	3	1	1	Operators have access to anemometer. And there decision is final	Yes

	wind near 38km/h are reached equipment will be deflated					
Petrol Blower/Generator Risk of fire or burning	Safety fencing erected around blower/generator. Suitable fire extinguisher supplied.	3	1	1	All spare fuel stored in suitable container and in a safe location. Units switched off during refuelling.	Yes
RISK ASSESSMENT CARRIED OUT BY:	Brian Auty	DATE: 16/03/2024		ANY OTHER ACTION REQUIRED:		Ensure that operators follow all 'Operating Instructions' verbally supplied

**THE ABOVE INFORMATION IS BASED ON MANUFACTURERS
CRITERIA AND EXPERIENCE FROM EXTENSIVE USE OF EQUIPMENT WE ARE ALSO RPII TRAINED AND CERTIFICATED AS WELL AS MEMBERS OF THE
NAIH.**

B.D.Auty

SIGNATURE _____

RISK ASSESSMENT – ULTIMATE WIPEOUT

HAZARD	EXISTING CONTROL MEASURES	HARM (1-5)	LIKELY HOOD (1-5)	RISK (1-5)	FURTHER CONTROLS TO REDUCE RISK	RISK ACCEPTABLE Y/N
Over enthusiastic participants	Adult supervision at all times	1	1	1		Yes
Participants being fallen on from others	Adult supervision at all times	2	1	2	No more than one on each podium. 6 PLAYERS MAXIMUM	Yes
Tripping over anchorage points/spare equipment/electrical cable	All anchor points used as per manufacturers instructions and spare equipment leads etc either stowed / erected safely	1	1	1	In event of large numbers of participants attending, additional safety fencing erected. Where possible electrical cable does not cross any public pathway. If unavoidable cable erected overhead or covered.	Yes
Body Injuries	Operated by trained staff only. Speed is fixed to maximum setting.	2	2	4	Wipeout Poles and Podiums constructed from foam to stop impact injuries	Yes
Petrol Blower/Generator Risk of fire or burning	Safety fencing erected around blower/generator . Suitable fire extinguisher supplied.	3	1	3	All spare fuel stored in suitable container and in a safe location. Units switched off during refuelling.	Yes
RISK ASSESSMENT CARRIED OUT BY:	Kym Barnes		DATE: 01/02/2023	ANY OTHER ACTION:		Ensure that operators follow all 'Operating Instructions' verbally



RISK ASSESSMENT – HUMAN WRECKING BALL

HAZARD	EXISTING CONTROL MEASURES	HARM (1-5)	LIKELY HOOD (1-5)	RISK (1-5)	FURTHER CONTROLS TO REDUCE RISK	RISK ACCEPTABLE Y/N
Over enthusiastic participants	Supervision at all times	1	1	1		YES
Participants being fallen on	Supervision at all times	1	1	1	No more than four on the inflatable at the same time. No sitting around the edges.	YES
Larger participants over powering smaller participants	Adult supervision at all times.	1	1	1	Participants put into groups of similar size.	YES
Tripping over anchorage points/spare equipment/electrical cable	All anchor points used as per manufacturers instructions and cables taped to the ground	1	1	1	In event of large numbers of participants attending, additional safety fencing erected. Where possible electrical cable does not cross any public pathway. If unavoidable cable erected overhead or covered.	YES
Facial hits	Participants briefing before participating	1	1	1		YES
RISK ASSESSMENT CARRIED OUT BY:	Brian Auty		DATE: 16/03/2023	ANY OTHER ACTION REQUIRED:	Ensure that operators follow all 'Operating Instructions' as supplied Or Active Hire to provide experienced staff for safe equipment supervision	

THE ABOVE INFORMATION IS BASED ON MAUFACTURERS CRITERIA AND EXPERIENCE FROM EXTENSIVE USE OF EQUIPMENT.

RISK ASSESSMENT – Velcro Darts

HAZARD	EXISTING CONTROL MEASURES	HARM (1-5)	LIKELY HOOD (1-5)	RISK (1-5)	FURTHER CONTROLS TO REDUCE RISK	RISK ACCEPTABLE Y/N
Over enthusiastic participants	Supervision at all times	1	1	1		Yes
Participants being hit by Velcro darts	Supervision at all times	2	1	1	No more than one player at one time	Yes
Darts Tipping	All anchor points in use	2	2	4	Maximum wind speeds of 24mph (subject to anchorage)	Yes
Velcro darts hitting spectators	Adult supervision at all times.	3	1	1	Operating away from public walkways and spectators not to walk across the playing area	Yes
Tripping over cables	All cables taped to the ground	1	1	1	In event of large numbers of participants attending, additional safety fencing erected. Where possible electrical cable does not cross any public pathway. If unavoidable cable erected overhead or covered.	Yes
RISK ASSESSMENT CARRIED OUT BY:	Kym Barnes		DATE: 01/02/2023	ANY OTHER ACTION REQUIRED:	Ensure that operators follow all 'Operating Instructions' as supplied	

THE ABOVE INFORMATION IS BASED ON MAUFACTURERS CRITERIA AND EXPERIENCE FROM EXTENSIVE USE OF EQUIPMENT.

SIGNATURE: K Barnes